

**Corporate Office**

Adtran, Inc.  
901 Explorer Boulevard  
Huntsville, AL 35806

**U.S. Mail**

P.O. Box 140000  
Huntsville, AL 35814-4000

**General Information**

800 9ADTRAN  
[info@adtran.com](mailto:info@adtran.com)  
[www.adtran.com](http://www.adtran.com)

**Pre-Sales**

**Technical Support**

800 615-1176  
[application.engineer@adtran.com](mailto:application.engineer@adtran.com)  
[www.adtran.com/support](http://www.adtran.com/support)

**Post-Sales**

**Technical Support**

888 423-8726  
[support@adtran.com](mailto:support@adtran.com)  
[www.adtran.com/support](http://www.adtran.com/support)

**ACES Help Desk**

888 874-ACES  
[aces@adtran.com](mailto:aces@adtran.com)  
[www.adtran.com/support](http://www.adtran.com/support)

# Release Notes

## AOS IAD Products

AOS Release A1.05.00  
November 14, 2008

# Contents

Contents.....	2
Supported Platforms for A1.05.00.....	3
Summary of New Features.....	4
Summary of Bug Fixes.....	6
Upgrade Instructions.....	8
Appendix A – Errata for A1.05.00.....	10
Appendix B – Related Documents.....	15

## Purpose and Supported Platforms

AOS Voice Products release A1 is a major system release that adds many new features and addresses customer issues that have been uncovered in previous code releases.

Release A1.05.00 is Generally Available code, meaning that it has been subjected to both Design Verification and Product Qualification testing. Results obtained during this testing have been evaluated and the code has been determined to be ready for General Availability. Caveats discovered during testing but not addressed in this build are listed in [Appendix A](#).

A listing of available documents for this release appears in [Appendix B](#). Configuration guides, white papers, data sheets, and other documentation may be found on Adtran's knowledge base, <http://kb.adtran.com>.

The contents of these release notes will focus on the Netvanta 6355 and the Total Access 900/900e series platforms. Netvanta 7100 release notes are available on the Adtran knowledge base at [kb.adtran.com](http://kb.adtran.com)

### Supported Platforms for A1.05.00

- **TA 900 Series** – VoIP Multiservice Access Gateway, single T1 interface
- **TA900e Series** – VoIP Multiservice Access Gateway, multi-T1 interface
- **NetVanta 6355** – Multiservice Access Gateway

## Summary of New Features

This section highlights the major features, commands, and behavioral changes for AOS A1.05.00. For a list of related documents, please see [Appendix B](#).

### Additions for All Voice Products in A1.05

#### Enhancement to SPRE code modes

Added enhancements to SPRE code modes to allow individual SPRE codes to function in a different mode than the mode that is globally defined. Locally handled SPRE codes can also be remapped to different functions.

#### Additional Features

- Added config option “voice disconnect-mode fast-busy” to play reorder tone instead of dialtone after an analog call is disconnected by the remote party.
- Added config option “ip sip proxy failover accept-registrations” to allow the SIP proxy in the Adtran to respond to REGISTER messages when in permanent failover mode.

### Additions for All Voice Products in A1.04

#### Enhancement to Match / Substitution templates

The match / substitution templates now have the ability to match on \*. This will allow for the substitution of any dial string containing a \*.

### Additions for All Voice Products in A1.03

#### Sip Diversion

The Sip Diversion feature in A1.03 converts Redirecting Number IEs on a PRI trunk into Diversion headers on the SIP trunk, allowing the calling party information to be preserved. This functionality is performed automatically after upgrading to A1.03 or later.

### Additions for 2<sup>nd</sup> Gen TA 900/900e series in A1.02

#### MGCP – Media Gateway Control Protocol

MGCP is a newly added VoIP call control method available for 2<sup>nd</sup> generation TA 900s. FXS ports are the only available endpoints for MGCP. No T1 CAS or T1 PRI support will be provided in this release. Media will still be transported over RTP, as it currently is with our SIP implementation. SIP and MGCP can coexist on the same IAD at the same time (i.e. SIP used for PRI delivery while MGCP used for FXS delivery).

#### 3-Way Conferencing

Local 3-way conferencing is now supported in the 2<sup>nd</sup> gen TA 900 series. 3-way conferencing is only supported in 2<sup>nd</sup> generation TA 900s. The only local conferencing participants currently supported are FXS voice users. The IAD is limited to only 3 separate 3-way conferences at a time.

## **Additions for All Voice Products in A1.01**

### VQM – Voice Quality Monitoring

Ability to make VoIP quality measurements on RTP media flows terminated or passed through the IAD. Results will estimate MOS scores for particular calls as well as jitter buffer performance.

### Loopback Accounts

When the loopback account call is connected, the RTP audio is looped back. This will provide an easy method to verify proper operation and configuration during install, and can be used with VQM to troubleshoot network issues. This feature includes the ability to initiate SIP calls via the CLI.

### AWCP - ADTRAN Wireless Control Protocol

AWCP is a Layer 2 Control and Management protocol that enables the platform to act as a Wireless Access Controller for the Netvanta 150 Access Point. Up to eight Netvanta 150 Access Points can be configured and managed by the AC.

### Top Talkers

The NetFlow flows that are generating the heaviest system traffic are known as the "top talkers." The Top Talkers feature can be used for security monitoring or accounting purposes for top talkers, and matching and identifying key users of the network. This information can be exported into a NetFlow 9 CSV file.

### Full PRI support

All 23 B channels of a PRI can be used simultaneously. The number DSP resources are increasing from 16 to 24 channels on the RoHS-E1 units.

### Top visited websites

The top websites feature is designed to report top websites requested by users to system administrators. This feature is intended to be used in conjunction with the ip urfilter command so that customers without a Websense server will have a simple URL filtering package.

### Additional Features

- VRF aware DHCP server
- VRF aware firewall
- Portal-List(s) to assign username access to different portals (system applications such as http, telnet, ssh, ftp, and console). Previously, a username for ftp could also telnet or ssh into the unit.

## Summary of Bug Fixes

This section highlights major bug fixes in AOS version A1.05.00.

### ADSL 0/1 interface missing from interfaces lists

---

#### *Issue Detail*

- The ADSL interface was missing from the “show interfaces” CLI command and the physical interfaces page in the GUI. This issue has been addressed.

### Switchboard waits 3 seconds to route call when no CID name presented in SETUP

---

#### *Issue Detail*

- Previously, the Adtran unit would wait 3 seconds before routing a PRI call if the SETUP message from the connected PBX didn't contain the calling party name field. The purpose of this was to wait for a facility message from the PBX that would contain the calling party name. This caused an undesirable delay for certain PBXs that didn't support calling party name. The config option “[no] calling-party name-facility-timeout <0-5>” was added to change the length of the delay or to disable the delay all together. Also, the default timeout value is now 2 seconds. This issue has been addressed.

### Possible resource leak through transparent proxy

---

#### *Issue Detail*

- A SIP proxy resource leak would occur if a CANCEL was sent after an INVITE but before the proxy rollover timer expired (default of 3 seconds). This only affected calls with through the transparent proxy. This issue has been addressed.

### “ip sip proxy allowed-servers” improperly rejects SIP messages if server address is FQDN

---

#### *Issue Detail*

- If an “ip sip proxy allowed-servers” entry was defined as an FQDN instead of an IP address, messages destined for that particular server via transparent proxy would get improperly rejected. Allowed-servers defined as ip addresses would work properly. This issue has been addressed.

### Firewall associations for calls through SIP proxy limited to 32 seconds

---

#### *Issue Detail*

- Previously, firewall associations for IP addresses in an SDP were cached for 32s. This was problematic for reINVITEs where an IP address or port number in an SDP needed to be translated through the firewall more then 32 seconds after the call was setup. The command “ip rtp nat-session timeout <32-900>” was added to increase the amount of time before the nat session will timeout. This issue has been addressed.

### T1 0/3 and 0/4 configured as secondary timing source isn't maintained after a reboot

---

#### *Issue Detail*

- Setting T1 0/3 or 0/4 as secondary timing sources on the TA 900e series wasn't maintained after a reboot. This issue has been addressed.

## DSP resources are not released when allocated to analog FXS interfaces w/ modem-passthrough

---

### *Issue Detail*

- Each time a call was placed through an analog voice user that had modem-passthrough enabled, a DSP resource was permanently allocated to that port. Depending on how many voice users were defined, it was possible for customers using PRI or E&M trunks along with analog voice users to not have any resources available to place or receive any DSX trunk calls. This issue has always existed in AOS. This issue has been addressed.

## Possible reboot when SYN flood protection is enabled

---

### *Issue Detail*

- SYN flood protection is automatically enabled by the firewall when more than 80% of the possible firewall associations are being used. In rare cases, a reboot would occur if one of the active firewall associations timed out at the same time as SYN flood protection was enabled. This issue has been addressed.

## MGCP only: Local Connection Options TOS parameter results in wrong DSCP value being marked on RTP

---

### *Issue Detail*

- If the Local connection options in the MGCP header contained a type of service value, the incorrect DSCP value was tagged in RTP packets. This issue has been addressed.

## Problems with URI matching for SIP Proxy User Database

---

### *Issue Detail*

- If a SIP endpoint sent a REGISTER through the proxy that contained an r-instance value but that same endpoint didn't send the r-instance in an INVITE, the Proxy User Database lookup in the proxy wouldn't correctly match the two contact headers. This issue has been addressed.

## MGCP only: Hookflash events not sent correctly when using RFC 2833

---

### *Issue Detail*

- If the Adtran unit was configured for RFC 2833, the wrong signal state was sent in the 2833 packets when a hookflash was performed. This issue has been addressed.

## Possible issue with loading startup-config after boot

---

### *Issue Detail*

- In rare cases, the system parser responsible for loading the startup-config into memory could have incorrectly matched specific characters in the hostname of the unit as an end of file. This resulted in part of the startup configuration not being loaded into the running configuration. This issue has always existed in AOS. This issue has been addressed.

## Bellcore Distinctive Ring 4 & 5 Produces Normal Ring Cadence

---

### *Issue Detail*

- An alert-info header populated with <http://127.0.0.1/Bellcore-dr#> where # = 4,5 would still produce a standard two seconds on four seconds off ring cadence. This issue has been addressed.

### Extra byte for DMS100 included in NI2 Display IE

---

#### Issue Detail

- When the PRI switch type was configured for NI2, the 3<sup>rd</sup> byte in the facility IE was an undefined character per Q.931 spec. The ISDN stack was using the 4<sup>th</sup> byte as the beginning of the display for facility IE instead of the 3<sup>rd</sup>. In rare cases, the terminating PBX may have had trouble interpreting the erroneous character. This issue has been addressed.

### “voice modem-passthrough-mode” not maintained after a reboot

---

#### Issue Detail

- Setting the voice modem-passthrough-mode to inbound or outbound wasn't maintained after a reboot. This issue has been addressed.

## Upgrade Instructions

Several steps need to be taken to assure a valid upgrade. First, save your existing configuration to a tftp server. The command to execute this step is

```
Router# copy start tftp
```

You will be prompted for file names and the server address in the process.

Next, download AOS version A1.05.00 from the ADTRAN support website. When properly installed on your tftp server, the file will have the form "*product-version.biz*" where *product* is the platform name, and *version* is the AOS image version (A1.05.00) separated by hyphens instead of decimals.

From your privileged prompt:

```
Router# copy tftp flash
```

During the tftp download you will be prompted for the tftp server name, the tftp server file name, and finally the name you want to give the file once it is transferred to the on-board flash. The flash can hold up to eight megabytes of files, whether AOS or configuration files. Now from the Configuration prompt:

```
Router (config)# boot system flash filename.biz
```

The boot command tells the router which software on the flash to use as the boot up AOS. The router should now be rebooted with the privileged command

```
Router (config)# reload
```

When the unit reboots, it will be running AOS version A1.05.00.

## Appendix A – Errata for A1.05.00

The following is a list of errata that still exists in A1.05.00.

### **Start time for VQM RTP stats downloaded to .CSV file is inaccurate**

The value used for start time is a UTC time value, not the normal system time expected by the user. This issue has been addressed in A2.

### **SSH sessions are always listed as authentication in progress**

The "show users" command does not list the idle time of any SSH sessions. They are always listed as "authentication in progress" whether or not the remote users has authenticated. This issue has been addressed in A2.

### **Erroneous problem with Public Security zone**

If 802.1q sub-interfaces are assigned to the Ethernet port, the GUI system summary will report a problem with the Public security zone not being set correctly. The unit functions correctly, but the GUI has an issue detecting the VLAN sub-interface when sanity checking the configuration. This issue has been addressed in A2.

### **GUI Call Quality Stats page shows codec as 'undefined'**

In the GUI, Voice -> Call Quality Stats, codecs are displayed as 'undefined'. The CLI shows the correct output. This issue has been addressed in A2.

### **Trunk appearance leak on E&M wink trunk w/ dialtone enabled**

Enabling dialtone on E&M wink trunks requires a reboot to prevent the trunk appearance from locking up. After the initial reboot, all E&M wink trunk will function correctly. This issue has been addressed in A2.

### **“busy all now” on a SIP trunk does not work properly**

If the user enables "busy all now" on a SIP trunk, the first inbound call will receive a 486 Busy Here, but the second call will ring normally. Outbound calls result in an INVITE being sent out the SIP trunk, even though it should be busied out. This issue has been addressed in A2.

### **Question marks used for URL-based options are interpreted as context-sensitive help in the CLI**

Question marks can't be used in URL-based DHCP options. They are incorrectly interpreted as context sensitive help. This issue has been addressed in A2.

### **PPP: 'no shutdown' on enabled interface causes it to bounce**

Entering the "no shut" command on a PPP interface that has already establish a PPP connection will cause the interface to bounce and re-negotiate. This issue has been addressed in A2.

### **DNS proxy failover failure**

If a DNS request is sent through the DNS proxy of the Adtran unit to the primary public DNS server and the DNS server responds with a "destination unreachable", the secondary DNS server won't be queried. This issue has been addressed in A2.

### **A single T.38 FAX call does not work without disabling plc on the voice user**

Plc must be disabled for T.38 FAX to work properly. "No plc" on the voice user or trunk will disable packet loss concealment. This issue will be address in A2.

### **MGCP Inbound calls fail if LocalConnectionOptions are not present in CRCX**

If a create connection is sent from the call agent without the LocalConnectionOptions field in the MGCP header, the subsequent call will fail. This will be address in A2.

### **MGCP only: Caller-ID name "O" not properly translated to FSK tones**

When the Adtran unit receives a caller-ID name of "O" in the MGCP message, the proper tones are not sent to indicate that the CID name is "Unavailable". Instead, the CID name will display "O". This will be addressed in A2.

### **SIP to MGCP Ringback issue**

While placing a call from a SIP user to an MGCP endpoint on the same Adtran unit with both lines registered, the SIP user will not hear ringback. This is only an issue with a soft switch that instructs the MGCP endpoint to provide remote ringback in the signaling field of the MGCP message (i.e. S: rt@\$). This is also only an issue on hairpin calls.

### **1<sup>st</sup> gen 900/900e only: Possible issue with DTMF generation under heavy call load**

With more than 18 simultaneous calls connected on a 1st gen TA 900 or TA900e series IAD using G.729 codec, it is possible that DTMF tones will not be recognized by the terminating CPE due to an issue with the Adtran unit generating frequencies at 2804 Hz or higher under heavy call load. This degradation in tone generation cannot be heard by the human ear. With 23 simultaneous calls, the call completion rate to terminating CPE is approximately 99.5%. With 24 simultaneous calls, the call completion rate drops to approximately 97%.

### **MGCP Confirmation tone (g/cf and l/cf) does not work**

When the TA 900 receives an S: g/cf or an S: l/cf to play a confirmation tone, nothing is played out.

### **900e only: Channels on 2<sup>nd</sup> PRI fail to establish voice path**

Due to how resources are allocated from the DSPs on the 900e, only 32 simultaneous calls will connect over 2 PRI interfaces if the first 23 calls are brought up on T1 0/4. The next 9 calls that connect on T1 0/3, for a total of 32 simultaneous calls, will work correctly. Any subsequent simultaneous calls (more then 32) will experience no media cut through. Due to the order in which calls must be connected in order to experience this issue, there is a low risk of experiencing this problem in the field.

### **24th call cannot generate DTMF digits out DSX wink trunk due to resource limitation**

For all calls into an E&M wink trunk, a DSP resource is reserved for RTP during call setup. This could prevent a DSP resource from being available to generate DTMF for DNIS if 23 calls are already active. This only effects 1<sup>st</sup> gen TA 900 series products.

### **MGCP limited to 18 FXS G711 Hairpin calls when using T-1 as local media gateway**

The Adtran unit is limited to 18 FXS Hairpin calls when the MGCP voice gateway is pointed out the WAN interface. It has been verified that 24 Hairpin calls work when the gateway is pointing out the Ethernet interface.

### **Output of “show crypto” displays more VPN tunnels than are supported by the device**

We currently support 30 VPN tunnels on the 900 products. The output of “show crypto” displays 200 for IKE and 400 for IPSEC.

### **503 error on system summary page of GUI**

If a multi-link Frame Relay interface is configured, the System Summary page of the GUI will error out with a 503.

### **“copy http” command only works with FQDN when FQDN is not in the host table**

The copy http command only works with a FQDN if it is not currently in the host table. If the FQDN is already in the host table, the command will immediately exit with no error message.

### **Modem-passthrough does not work for ring-group users**

On calls placed into a ring group, no fax/modem detection resources are allocated. This will prevent the Adtran unit from automatically being able to switch to data mode for fax or modem calls.

### **Lost packets on “show voice quality-stats” doesn't match the “show media-gateway channel” stats**

The number of lost packets in the "show voice quality-stats" doesn't match up with "show media-gateway channel" stats in the following scenario: 2 G.729 calls are brought up over a 2xT1 MLPPP bundle. With both calls up, the media-gateway counters were cleared and then t1 0/1 was pulled and then immediately plugged back in (it wasn't unplugged long enough to cause any errors to display on the console). After the T1 was plugged back in, the lost packets in the "show voice quality-stats" are different than the lost packets in the "show media-gateway channel" stats.

### **Number of lost packets is larger than the number of expected packets**

In rare cases, the number of lost packets logged by the “show voice quality-stats” could be larger than the number of expected packets for a given call.

### **Not sending “NOT ENDtoEND ISDN” in ALERTING message on PRI to SIP calls in response to a 180**

The Adtran unit currently doesn't send "Description:NOT ENDtoEND ISDN" in the ALERTING out the PRI to the PBX in response to a 180 Ringing from the SIP trunk.

### **6355 only: Overhead Paging doesn't work**

Calls to the overhead paging extensions do not work properly.

### **T1 in Yellow Alarm Causes 503 on System Summary page of GUI**

If one of the T1s on the Adtran unit is receiving a yellow alarm, the system summary screen sends back a 503 server error. Once the alarm clears, it works as it should.

### **Problems with Total Access Config Wizard in the GUI**

The Total Access Config Wizard in the system menu of the GUI won't complete past the VoIP section.

### **RTP is not allowed through the firewall when NAT is performed on inbound calls to a SIP user with no SDP in the INVITE**

If the SDP for an inbound call is not sent until the SIP Server ACKs the 200 OK when the called party answers, the firewall will not open a hole for RTP resulting in no audio.

### **“Voice Quality-Stats” Jitter Buffer Average is greater than max value**

In rare instances, the output of a "show voice quality-stats" could show that the average size of the jitter buffer is higher than the max value.

### **T.38 stack does not send any packets when a Super G3 fax is used**

When a Super G3 fax machine is used behind The Adtran unit, T38 will not function properly.

### **One-way Audio - Audio Codec Negotiation Problem**

If the Adtran unit receives an SDP where the codec preference order in the media field has DTMF relay before g.711 or g.729 (i.e. m=audio 31794 RTP/AVP 101 0), media won't be sent properly resulting in one way audio.

### **Jitter Buffer Mode shows adaptive after modem-passthrough detects a data call**

After modem-passthrough has switched the user to data mode, the jitter buffer mode still shows adaptive instead of fixed under "show voice quality-stats [id]".

### **http secure server could become unresponsive**

In rare cases, the secure http server in the Adtran unit could become unresponsive, preventing https access. CLI access is not affected.

### **MGCP possible issue with 3-way conferencing**

The issue occurs in the following scenario: Phone A calls phone B, then phone B flashes and calls phone C. If phone B flashes BEFORE phone C answers (so that A and B can talk while waiting for C), the three-way conference will fail. After Phone C answers, phone A and B will continue to hear ringback. If phone B flashes AFTER phone C answers, then three-way conference works.

### **Calls to a UCD ring group will result in no talk path**

Calls to a ring group with uniform call distribution configured will result in no talk path in either direction.

### **900e / 6355 only: Possible problem with VPN connection between Ethernet ports**

Under heavy load, the Adtran unit cannot service packets at the same rate needed for the packets to be encrypted, causing the unit to drop packets. Input decryption errors are reported to the terminal due to encrypted packets missing in the sequence. Throughput performance is slightly affected.

### **“debug IP packet VRF <vrf>” provides no output after Fast Flow enabled on interfaces**

"Debug IP packet vrf <vrf>" on the the non-default vrf does not display any data after "ip ffe" is enabled on the ethernet and MFR interfaces. "Debug ip packet" on the default vrf will continue to relay information to the terminal.

### **H.323 video conference fails with H.323 ALG**

Incorrect passives are formed when the media address specified in an openLogicalChannel or openLogicalChannelAck H.245 message differs from the sender of the H.245 signaling.

**Redirect with 302 Moved Temp fails**

If the SIP server responds to an INVITE from the Adtran unit with a 302 to redirect a call, the Adtran is not able to correctly resolve the address in the contact field causing the call to fail.

## Appendix B – Related Documents

For configuration guides, installation guides, white papers and more, visit ADTRAN's knowledge base at <http://kb.adtran.com>.

AOS A1 Command Line Reference Guide (13MB file) –  
<http://kb.adtran.com/article.asp?article=2219&p=2>

Voice Quality Monitoring Config Guide -  
<http://kb.adtran.com/article.asp?article=2262&p=2>

[Video]Understanding Voice Quality Monitoring in AOS -  
<http://kb.adtran.com/article.asp?article=2296&p=2>

Integrated Traffic Monitoring Config Guide (Top Talkers Support) -  
<http://kb.adtran.com/article.asp?article=2157&p=2>

Multi-VRF Config Guide –  
<http://kb.adtran.com/article.asp?article=2156&p=2>

URL Filtering/Top Websites Reporting Config Guide -  
<http://kb.adtran.com/article.asp?article=2158&p=2>

AOS Wireless Config Guide –  
<http://kb.adtran.com/article.asp?article=2078&p=2>